

TIP-SOP-001 - Creating a Safe Work Zone

Sop Title:	Creating a Safe Work Zone	Sop No:	TIP-SOP-001	
Sop Location:	Multiple	Associated SWMS:	TIP-SWMS-001	
Date of Issue:	11/02/2025	Next Review Date:	30/01/2027	
Issue Version:	1.0	Authorised By:	Jeremy Wee	
Frequency:	When required			
Purpose:	Create safe work zone			
Responsibility:	Tipper driver	Requirements:	- Witches hats - Breakdown triangles	
Compliance:		PPE Requirements:		
- WHS Act 2011 - WHS Regulation 2017				

Step	Activity	Safety/ Quality/ Performance Notes
1	Check the work area for potential traffic hazards	 Positive communications with other vehicle operators Ensure the correct PPE is worn Be aware of your surroundings
2	Access the breakdown triangles or witches hats Create safe work zone	 Minimum size of Safe Work Zone is 2 metres Use breakdown triangles or witches hats Increase the size of the Safe Work Zone as necessary
3	Place the breakdown triangles or witches hats at the corners of the required Safe Work Zone	- Ensure correct manual handling technique is used - Ensure the correct PPE is worn - Be aware of your surroundings
4	Control entry to the Safe Work Zone	 You are responsible for controlling entry to Safe Work Zone Ensure positive communications with other vehicle operators and pedestrians before allowing others to enter the area Replace witches hats/breakdown triangles once other vehicles, machinery, pedestrians have left the Safe Work Zone Continue to monitor the area whilst you are working Stop work immediately and move to a safe area if anyone enters your Safe Work Zone without authorisation
5	Remove breakdown triangles or witches hats	- Ensure correct manual handling technique is used - Ensure the correct PPE is worn - Be aware of your surroundings - Positive communications



TIP-SOP-001 - Creating a Safe Work Zone

Prepared By / Review Team				
Name	Position	Signature	Date	
Marko Kasap	Driver Trainer / Safety Committee Member	MX 14	11/02/2025	
Victoria Piserchia	Supervisor	(D)	11/02/2025	

Authorisation				
I have checked this Standard Operating Procedure (SOP) and confirm that it is authorised for use.				
Person supervising the work	Signature	Date		
Jeremy Wee	ann	11/02/2025		